



POWER DRILL - STUB / 3 x D

PDS ...series



EDP. No.	Dia.	L ₁	L ₂	D ₂	STOCK	
PDS010	1	8	38	3	•	
PDS011	1.1	10	42		•	
PDS012	1.2				•	
PDS013	1.3				•	
PDS014	1.4				•	
PDS015	1.5				•	
PDS016	1.6				•	
PDS017	1.7				•	
PDS018	1.8				•	
PDS019	1.9				13	•
PDS 020	2.0			14	50	3
PDS 021	2.1	•				
PDS 022	2.2	•				
PDS 023	2.3	•				
PDS 024	2.4	•				
PDS 025	2.5	•				
PDS 026	2.6	•				
PDS 027	2.7	•				
PDS 028	2.8	•				
PDS 029	2.9	•				
PDS 030	3.0	18	60	•		
PDS 031	3.1	22	60	4	•	
PDS 032	3.2				•	
PDS 033	3.3				•	
PDS 034	3.4				•	
PDS 035	3.5				•	
PDS 036	3.6				•	
PDS 037	3.7				•	
PDS 038	3.8				•	
PDS 039	3.9				24	•
PDS 040	4.0				•	
PDS 041	4.1	24	62	5	•	
PDS 042	4.2	26			•	
PDS 043	4.3				•	
PDS 044	4.4				•	
PDS 045	4.5				•	
PDS 046	4.6				•	
PDS 047	4.7				•	
PDS 048	4.8				•	
PDS 049	4.9				•	
PDS 050	5.0				•	
PDS 051	5.1		28	66	6	•

EDP. No.	Dia.	L ₁	L ₂	D ₂	STOCK			
PDS 052	5.2	28	66	6	•			
PDS 053	5.3				•			
PDS 054	5.4				•			
PDS 055	5.5				•			
PDS 056	5.6				•			
PDS 057	5.7	30	66	6	•			
PDS 058	5.8				•			
PDS 059	5.9				•			
PDS 060	6.0				•			
PDS 061	6.1				34	74	7	•
PDS 062	6.2	•						
PDS 063	6.3	•						
PDS 064	6.4	•						
PDS 065	6.5	•						
PDS 066	6.6	•						
PDS 067	6.7	37	74	7				•
PDS 068	6.8							•
PDS 069	6.9							•
PDS 070	7.0							•
PDS 071	7.1	40	79	8	•			
PDS 072	7.2				•			
PDS 073	7.3				•			
PDS 074	7.4				•			
PDS 075	7.5				•			
PDS 076	7.6				•			
PDS 077	7.7				•			
PDS 078	7.8				•			
PDS 079	7.9				•			
PDS 080	8.0				•			
PDS 081	8.1	43	84	9	•			
PDS 082	8.2				•			
PDS 083	8.3				•			
PDS 084	8.4				•			
PDS 085	8.5				•			
PDS 086	8.6				•			
PDS 087	8.7				•			
PDS 088	8.8				•			
PDS 089	8.9				•			
PDS 090	9.0				•			
PDS 091	9.1	47	89	10	•			
PDS 092	9.2				•			
PDS 093	9.3				•			